HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

QUARRY VISITOR CENTER Dinosaur National Monument U.S. Highway 40, 8 miles north of Jensen Jensen vicinity Uintah County Utah HABS UT-138

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Roger Whitacre, photographer, September 2008

UT-138-1	Looking southwest, Visitor Center, general setting
UT-138-2	Looking east, general setting, showing rear and side of building
UT-138-3	Looking west, building front, Exhibit Shelter is on right, Administrative Wing is on left
UT-138-4	Looking northwest, building front
UT-138-5	Looking north, building front, angle view
UT-138-6	Looking northwest, building side, showing cylindrical Administrative Wing and ramp on right and South Wing on left
UT-138-7	Looking northwest, serpentine entry ramp and Administrative Wing
UT-138-8	Looking north, Administrative Wing close-up, showing damage; with monitor strips on wall cracks
UT-138-9	Looking east, building rear, Exhibit Shelter on left, one-story South Wing on right
UT-138-10	Looking northeast, rear wall, with door
UT-138-11	Looking west, Exhibit Shelter, showing Upper Visitor Gallery on left, and quarry wall on right
UT-138-12	Looking northeast, lower level exhibit space, showing quarry wall and front wall
UT-138-13	Looking north as quarry wall from Upper Visitor Gallery, near west wall
UT-138-14	Looking west, first floor, South Wing, window to Paleontology Lab
UT-138-15	Looking southeast, first floor, Administrative Wing interior
UT-138-16	Looking west, first floor, South Wing, hallway to offices, library, and Paleontology Lab
UT-138-17	Looking west, first floor, South Wing, library

UT-138-18	Looking east, first floor, South Wing, Paleontology Lab, showing shift of floor, seen in door jamb
UT-138-19	Looking northwest, first floor, South Wing, Paleontology Lab. The quarry wall can be seen through the window
UT-138-20	Looking west, first floor, Exhibit Shelter, showing stairway to second floor exhibit area, and first floor rear door
UT-138-21	Looking east, second floor, Exhibit Shelter with quarry wall on left and Upper Visitor Gallery on right
UT-138-22	Looking southeast, second floor, Administrative Wing interior

The original, historic documents shown in photographs below are located in the National Park Service, Denver Service Center, Technical Information Center, Denver, Colorado. They are in the public domain.

UT-138-23	Original Drawing: Design Perspective View
UT-138-24	Original Construction Drawing: Site Plan
UT-138-25	Original Construction Drawing: Plan at Lower Level
UT-138-26	Original Construction Drawing: Plan at Upper Level
UT-138-27	Original Construction Drawing: Plans of Circular Element, Lower Level and Upper Level
UT-138-28	Original Construction Drawing: Exterior Elevations, North and South
UT-138-29	Original Construction Drawing: South Elevation
UT-138-30	Original Construction Drawing: Exterior Elevations, East and West
UT-138-31	Original Construction Drawing: West Elevation and East Elevation
UT-138-32	Original Construction Drawing: Section Through Building
UT-138-33	Original Construction Drawing: General Cross Section
UT-138-34	Original Construction Drawing: General Cross Section, showing sun angles
UT-138-35	Original Construction Drawing: Foundation Plan and Notes
UT-138-36	Original Construction Drawing: Roof & Floor Framing Plans and Details, Roof Framing Plan Administration Area, and Second Floor Framing Plan Administration Area
UT-138-37	Original Construction Drawing: Typical Cross Section & Details
UT-138-38	Original Construction Drawing: Column and Beam Connection Detail
UT-138-39	Original Construction Drawing: Foundation Details & Schedule

QUARRY VISITOR CENTER HABS UT-138 INDEX TO PHOTOGRAPHS (Page 3)

UT-138-40	Original Construction Drawing: Exterior Details, Elevation of Typical Window Unit, Section Through Typical Window Unit, Section Through Skylight
UT-138-41	Original Construction Drawing: Miscellaneous Details
UT-138-42	Original Construction Drawing: Stair Details